

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,028 B2
APPLICATION NO. : 10/624327
DATED : October 4, 2005
INVENTOR(S) : Lee et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10.

Line 45 should read -- wherein the plate line covers sidewalls of the hydrogen --

Column 11.

Line 1 should read -- 7. The device as claimed in claim 1, wherein the ferro- --


Line 15 should read -- 11. The device as claimed in claim 1, wherein the plate line --

Column 12.

Line 53 should read -- (Ba, Sr)TiO₃, Pb(Zr,Ti)O₃, SrBi₂Ta₂O₉, (Pb,La)(Zr,Ti)O₃, --

Signed and Sealed this

First Day of May, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office